FIELD INSPECTION REPORT

Date of Inspection: 62/12/2020			District: Jounne	
Division: Jamus			Length (km): 1.679 (xxx)	
		Sondipi Kou	znadenel To "Chor	olea.
	Programme:	MAINTENANCE	In-140N	7 EA E
Package No.: MR. N/19-20-Jamui 2 Road Id No.: 2841 10 3 Status of the Project: Ongoing/Completed/Under Maintenance			7347	
	a case of:		Jp gradation/ Maintenance	
Sl. No.	a case or.	BY TOUR WHEN		Remarks
1.	Pavement			
a)	Road Junction condition			SAY
b)	Condition of Surfacing			S/U
c)	Riding Quality			SAU
d)	Road Camber			Say
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/ SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			J.
a)	Status of ATR	's & any others		N.A

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

(Ashok Kumzuz Arya.) A.E. RWD, Lamipus Aug 112/2

(Signature Cutive Engineer