FIELD INSPECTION REPORT

		MAINTENANCE VIA NASTICE	sha New
	rogramme:	19-20- James 16 Road Id No.: 284/103	
atus of	the Project:	Ongoing/Completed/Under Maintenance	2001
	case of:	New Connectivity/Up gradation/ Maintenance	
I. No.	in the standard	Parameters to she checked	Remarks
1.	Pavement	Samuel State of the State of th	Mil
a)	Road Junction condition		
b)	Condition of Surfacing		SAU
	Riding Quality		
c)	Road Camber		
d) e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
yre i	Contraction Joints provided or not (CC Pavement)		
<u>t)</u>	Compaction of flank/slope & raincuts if any		
g) 2.	Cross Drainage		Ro Le
an provide alfaire	Condition of head walls in Hume pipe culverts including its painting		
a)	Condition of Abutment & Wing walls, Slab in RCC culverts		
b)	Condition of railings/slab/approach for Bridges		
c) 3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		YesANo
4.	Complianc	e History	
a)	ada and the way of the same of the	Status of ATR's & any others	
Overa	1 Rating	Satisfactory (S)	5.
	Satisfactory but requires Improvement (SRI)		<u> </u>
		Unsatisfactory (U)	

NAME:

RWD Works Division, Jamui

(M.M.IELAM) (Ashok Kumas Asya.)

TE A.E. RWD, Lannipus