FIELD INSPECTION REPORT

Date of Ir	nspection: 3/12/2020	District: Patra.	
Division :	: Palma.	Length (km): 0.500 (m
Scheme/I	Programme: MAINTENANCE	andh to Kankot	iya God
	No.: MR-N-201-20 Patral		_
CONTRACTOR OF THE PARTY OF THE	The first of the f	xd/Under Maintenance (New 1	namo ten
PRENIOUS LETT.	A Company of the Comp	Up gradation/ Maintenance	
Sl. No.	Parameters to	o be checked	Remarks
11.	Payement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		₹⁄U
d)	Road Camber 🌵		₹⁄U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Ýes/No
2.	Cross Drainage — N	A	
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		5,5,4,0
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Company of the second company of the second	10 '	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	yes.
Unsatisfactory (U)	
s and state of y (0)	

NAME: Fratall Changra Trabhet.

DESIGNATION: A.E

(Signature) (Signature)