

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District :	Mungel
Division :		Length (km) :	2.025
Name of the Road :	Machidih RFO Road Dullah via Weste sambar Road		
Scheme/Programme :	MAINTENANCE		
Package No. :	No	Road Id No. :	S No - 3
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	work in progress	S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality	DO	S/U
d)	Road Camber	DO	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	DO	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	DO	Yes/No
g)	Compaction of flank/slope & rainouts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	work in progress	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	DO	S/SRI/U
c)	Condition of railings/slab approach for Bridges	DO	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 700m stones/Pavement road markings are provided and maintained	work in progress	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	work in progress	(S)
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

shailendra k.

NAME:

J-E

(Signature)