


FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Mungra
Division :		Length (km):	1.250
Name of the Road:	Mafwa Jozari to Khairda via Sathi Road		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	No	Road Id No.:	S.H.V. 41
Status of the Project:	✓ Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	work not start	S/U
b)	Condition of Surfacing	do	S/U
c)	Riding Quality	do	S/U
d)	Road Camber	do	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	do	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	do	Yes/No
g)	Compaction of flank/slope & raincuts if any	do	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	do	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	do	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	do	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	do	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S)	work not started till
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

Shailendra K.
NAME: J-C