

FIELD INSPECTION REPORT

Date of Inspection :	2/12/2020	District:	Mungwa
Division :	Kharagpur-Taapra	Length (km):	2.02
Name of the Road:	Amiya - Dholbahi		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	NO ✓	Road Id No.:	S-40-4
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	work in progress S/U
b)	Condition of Surfacing	DO S/U
c)	Riding Quality	DO S/U
d)	Road Camber	DO S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	No P.C.C. found Yes/No
f)	Contraction Joints provided or not (CC Pavement)	No P.C.C. found Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	work in progress Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	work in progress	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: