

# FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District :	Munger
Division :	Kharagpur - Tarapur	Length (Km) :	1.00 Km
Name of the Road :	Const. of P.C.C road at Ghodhobha Asiwashi hla.		
Scheme/Programme :	MAINTENANCE	NMP 2018	
Package No. :		Road Id No. :	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1	<b>Pavement</b>		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank/slope & raincuts if any	✓Yes/No	
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	<b>Road Furniture</b>		
a)	Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4	<b>Compliance History</b>		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S) ✓	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME : Sukesh Kumar  
DESIGNATION : A.E

S. Kumar  
3.12.2020  
(Signature)