

FIELD INSPECTION REPORT

| | | | |
|-------------------------|--|---------------|---------|
| Date of Inspection : | 3.12.2020 | District : | Munger |
| Division : | Kharagpur - Tarapur | Length (Km) : | 1.1 Km. |
| Name of the Road : | Const. of P.C.C road at Fulbariya Gram. | | |
| Scheme/Programme : | MAINTENANCE / NMP 2018. | | |
| Package No. : | | Road Id No. : | |
| Status of the Project : | Ongoing/Completed/Under Maintenance <input checked="" type="checkbox"/> | | |
| Work is a case of : | New Connectivity/Up gradation/Maintenance <input checked="" type="checkbox"/> | | |
| Sl. No. | Parameters to be checked | Remarks | |
| 1 | Pavement | | |
| a) | Road Junction condition | ✓S/U | |
| b) | Condition of Surfacing | ✓S/U | |
| c) | Riding Quality | ✓S/U | |
| d) | Road Camber | ✓S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | ✓Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | ✓Yes/No | |
| g) | Compaction of flank/slope & raincuts if any | ✓Yes/No | |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | } NA |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3 | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary board/Km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No | |
| 4 | Compliance History | | |
| a) | Status of ATR's & any others | No. | |

Overall Rating :

| | |
|--|--|
| Satisfactory (S) <input checked="" type="checkbox"/> | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

NAME: Suresh Kumar
DESIGNATION: A.E

S. K. K. / 3.12.2020.
(Signature)