

FIELD INSPECTION REPORT

Date of Inspection :	District:	Munger
Division : Jamalpur	Length (km):	1300 M
Name of the Road: बौद्ध च्यामरा मुस्लिम रोड बर्नाला गॉवडे बाइपास सीमा रा	Scheme/Programme:	MAINTENANCE MR
Package No.:	Road Id No.:	projID-20803708146
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U .
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Y
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Nees
2-12-2020
(Signature)

NAME: