## FIELD INSPECTION REPORT

Date of Inspection :		District:	
Division:		Length (km): 1. 800 km	
f the Road: 139	santi Talav Path Di	IV ke somme Hoji Sujan Pu	th ke Muser
Programme:	MAINTENANCE	MR	
Package No.:		Road Id No.: 20803708151	
k is a case of: New Connectivity/Up gradation/ Maintenance		1	
	Parameters to be	checked	Remarks
Pavement			And the
Road Junction condition			S/U
Condition of Surfacing			S/U <
Riding Quality			S/U
Road Camber		S/U S	
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Contraction Joints provided or not (CC Pavement)		Yes/No	
Compaction of flank/slope & raincuts if any		Yes/No	
Cross Draina	<b>je</b>		
Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRIAU S	
Condition of railings/slab/approach for Bridges		S/SRI/U	
Road Furnitu	æ		
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No S
Compliance H	lstory		
Status of ATR'	s & any others		
֡	f the Road: 139 /Programme: No.: If the Project: a case of: Pavement Road Junction Condition of S Riding Quality Road Camber Whether free aggregates in of Contraction Jo Compaction of Cross Drainag Condition of A Condition of ra Road Furnitus Whether sign stones/Pavement	f the Road: 139590 H Talay Path D/Programme:   MAINTENANCE   No.:   I the Project:   Ongoing/Completed/U a case of:   New Connectivity/Up	Length (km):   Note

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	The second section is the second of the second seco
Unsatisfactory (U)	

	Unsatisfactory (U)	
	The state of the s	
		2-12-20
		(Signature)
NAME:		
PROVANCE MEAN		