

FIELD INSPECTION REPORT

Date of Inspection:	3/12/2020	District:	Mungelo
Division:	Kharagpur - Tarpur	Length (km):	3.30 km
Name of the Road:	Conit dr Road from mukwa - caradhi Rto Road to Misra Pur Badabaka		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	NO ✓	Road Id No.:	S.N. 6
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	work in progress S/U
b)	Condition of Surfacing	DO S/U
c)	Riding Quality	DO S/U
d)	Road Camber	DO S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	DO Yes/No
f)	Contraction Joints provided or not (CC Pavement)	DO Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/ work in progress
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	DO S/SRI/U
c)	Condition of railings/slab/approach for Bridges	DO S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No work in progress
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	work in progress	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: shankar k. j.c.

(Signature)