

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	MUNHUR
Division :	Ichargpur	Length (km):	2.08 2.08 Km
Name of the Road:	Const. of Makwa Shantinagar R.O. se 1920m Tak		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	NO.	Road Id No.:	S.No. → 2.08
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	work not start S/U
b)	Condition of Surfacing	DO S/U
c)	Riding Quality	DO S/U
d)	Road Camber	DO S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	DO Yes/No
f)	Contraction Joints provided or not (CC Pavement)	DO Yes/No
g)	Compaction of flank/slope & rineuts if any	DO Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	DO S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	DO S/SRI/U
c)	Condition of railings/slab/approach for Bridges	DO S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	DO Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No.

Overall Rating :

Satisfactory (S)	work not started yet.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shakti Kumar

Shakti Kumar

(Signature)

NAME:

S.E.