

# FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020 District: Mungel  
 Division : Kharsa Pur - Tapa Pur Length (km): 3.50  
 Name of the Road: Masumganj se Madhotpur Said Pur se Kamra  
 Scheme/Programme: MAINTENANCE  
 Package No.: Road Id No.: 20803808043  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No. | Parameters to be checked                                                                                             | Remarks   |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------|
| 1.      | <b>Pavement</b>                                                                                                      |           |
| a)      | Road Junction condition                                                                                              | ✓ S/U     |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U     |
| c)      | Riding Quality                                                                                                       | ✓ S/U     |
| d)      | Road Camber                                                                                                          | ✓ S/U     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | ✓ Yes/No  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | ✓ Yes/No  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No  |
| 2.      | <b>Cross Drainage</b>                                                                                                |           |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | ✓ S/SRI/U |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | ✓ S/SRI/U |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U   |
| 3.      | <b>Road Furniture</b>                                                                                                |           |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No  |
| 4.      | <b>Compliance History</b>                                                                                            |           |
| a)      | Status of ATR's & any others                                                                                         | No        |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S)                            | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

Shailendra K.

NAME:

J-E.

(Signature)