FIELD INSPECTION REPORT

	Inspection : C	The second secon	Jasonel	4 1	
Division: James Length (km):					Pard
	f the Road: Ja	mui Khazagpuz Mo	un Road To	Bela Me	Bar Mil
	Programme:	MAINTENANCE'	Vo.: 208041011	NE4	Bangardih
	f the Project:	Ongoing/Completed/Under Mai		75.7	
	a case of:	New Connectivity/Up gradation/ Maintenance			
Sl. No.	Company of the	Parameters to be checked		Remarks	
1.	Pavement				
a)	Road Junction	Road Junction condition			
b)	Condition of Surfacing			SAY	
c)	Riding Quality			SAU	
d)	Road Camber			SAU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	N/A
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	NA
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/ SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a) ,	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			YesANo	
4.	Compliance History				
a)	Status of ATI	Status of ATR's & any others			
Overall	Rating :				
Overall	raing .	Satisfactory (S)		S	
		Satisfactory but requires Im	provement (SRI)		No. 1 8

NI A B C C

(M.M. Stad (Ashale human Ange)

SE A. E. RWD, Laxmin

Unsatisfactory (U)

Unh 2/12/20

(S**Executive** Engineer **EXECUTE** Works Division, Jamui