

FIELD INSPECTION REPORT

Date of Inspection :- 21/2/20		District :- Mahesana	
Division :- Mahesana		Length (Km) :- 2.230 Km	
Name of Road :- NH 31 Bainsandvali Chowd Se Chavats Se Harani PE O Path Mansamatti Karyga			
Scheme/Programme :- MR (3050) New		Maintenance	
Package No. :-		Road ID No. :-	
Status of Project :- Complete		Ongoing/Complete/Under Maintenance	
Work is a case of :-		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction Condition	S	S/U
b)	Condition of Surface	S	S/U
c)	Riding Quality	S	S/U
d)	Road Camber	S	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A.	Yes/No
f)	Contruction joints provided or not (CC Pavement)	Yes	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	N/A.	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A	S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200 m stone/Pavement road markings are provided and maintained	Yes	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S) ✓	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)