

FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020		District: Katihar.		Division: Katihar	
Name of Road:		NH 31 Chethariya pir to Bisahariga via Sisiga Length - 4.63 KM			
Scheme/ Programme:		MAINTENANCE			
Package No.		Road ID No. 21105508077			
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance			
Sl.No	Parameters to be Checked				Remarks
1	Pavement				
a)	Road Junction Condition				S/U
b)	Condition of Surfacing				S/U
c)	Riding Quality				S/U
d)	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				Yes/No
f)	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2	Cross Drainage				
a)	Condition of headwalls in Humepipe culverts including its painting				S/SRI/U NA
b)	Condition of Abutment & Wings walls, Slab in RCC culverts				S/SRI/U NA
c)	Condition of railings/slabs/approach for Bridges				S/SRI/U NA
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.				Yes/No
4	Compliance History				
a)	Status of ATR & any others				NA
Overall Grading:		Satisfactory (S)			S
		Satisfactory but requires Improvement(SRI)			
		Unsatisfactory (U)			

Name: CHANDRAHAS KUMAR
Designation:
 Executive Engineer,
 R.W.D. Works Div., Katihar


 (Signature)