

### FIELD INSPECTION REPORT

<b>Date of Inspection:</b> 2-12-2020		<b>District:</b> Katihar.		<b>Div. -</b> Katihar	
<b>Name of Road:</b>		Kursela Railway Station se Khoriya Jane wali Path Ki Marammati Length - 1.10 KM			
<b>Scheme/ Programme:</b>		MAINTENANCE			
<b>Package No.</b>		<b>Road ID No.</b> 21105508081			
<b>Status of the Project:</b>		Ongoing/Completed/Under Maintenance			
<b>Work is a case of:</b>		New Connectivity/ Up Gradation/ Maintenance			
<b>SLNo</b>	<b>Parameters to be Checked</b>			<b>Remarks</b>	
<b>1</b>	<b>Pavement</b>				
a)	Road Junction Condition			✓S/U	
b)	Condition of Surfacing			✓S/U	
c)	Riding Quality			✓S/U	
d)	Road Camber			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No NA	
g)	Compaction of flank/slope & raincuts if any			✓Yes/No	
<b>2</b>	<b>Cross Drainage</b>				
a)	Condition of headwalls in Humepipe culverts including its painting			S/SRI/U NA	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts			S/SRI/U NA	
c)	Condition of railings/slabs/approach for Bridges			S/SRI/U NA	
<b>3</b>	<b>Road Furniture</b>				
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.			✓Yes/No	
<b>4</b>	<b>Compliance History</b>				
a)	Status of ATR & any others			NA	
<b>Overall Grading:</b>		Satisfactory (S)		S	
		Satisfactory but requires Improvement(SRI)			
		Unsatisfactory (U)			

Name: CHANDRAHAS KUMAR  
 Designation-  
 Executive Engineer,  
 R.W.D. Works Div., Katihar

(Signature) 2/12/2020