

# FIELD INSPECTION REPORT

| Date of Inspection : 03-12-2020                                               |                                                                                                                      | District: Katihar  |
|-------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------|
| Division : Barsoi                                                             |                                                                                                                      | Length (km): 4.370 |
| Name of the Road: Sonaili kamru Baghela (Pahlagash) Road, Panchayat Pahlagash |                                                                                                                      |                    |
| Scheme/Programme: MAINTENANCE                                                 |                                                                                                                      |                    |
| Package No.:                                                                  |                                                                                                                      | Road Id No.:       |
| Status of the Project: Ongoing/Completed/Under Maintenance                    |                                                                                                                      |                    |
| Work is a case of: New Connectivity/Up gradation/ Maintenance                 |                                                                                                                      |                    |
| Sl. No.                                                                       | Parameters to be checked                                                                                             | Remarks            |
| 1.                                                                            | Pavement                                                                                                             |                    |
| a)                                                                            | Road Junction condition                                                                                              | S/U/NA ✓           |
| b)                                                                            | Condition of Surfacing                                                                                               | S/U/NA ✓           |
| c)                                                                            | Riding Quality                                                                                                       | S/U/NA ✓           |
| d)                                                                            | Road Camber                                                                                                          | S/U/NA ✓           |
| e)                                                                            | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No/NA ✓        |
| f)                                                                            | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No/NA ✓        |
| g)                                                                            | Compaction of flank/slope & raincuts if any                                                                          | Yes/No/NA ✓        |
| 2.                                                                            | Cross Drainage                                                                                                       |                    |
| a)                                                                            | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U/NA ✓       |
| b)                                                                            | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U/NA ✓       |
| c)                                                                            | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U/NA ✓       |
| 3.                                                                            | Road Furniture                                                                                                       |                    |
| a)                                                                            | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No/NA ✓        |
| 4.                                                                            | Compliance History                                                                                                   |                    |
| a)                                                                            | Status of ATR's & any others                                                                                         | NO                 |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S) ✓                          | "S" |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

(Signature)

NAME: SANJAY KUMAR ROY,

DESIGNATION: E.E.

RWD, BARSOI