FIELD INSPECTION REPORT

Date of Inspection: - 02-12-20			District: - Kighanganj		
Division: - Kishanganj - I			District: - Kighanganij Length(km): 6.00 KIM		
		60- TOB TO	Dubadompi		
	/Programme:	MAINTENANCE			
Package	P No .: MR-N/1	9-20/ Kishanjami	1/06 Road Id No .: 21205802058		
	of the Project:		eted /Under Maintenance		
Work is	a case of:		ty/ Up gradation / Maintenance		
\$1. No	Parameters to be checked		s to be checked	Remarks	
1.	Pavement			~S/U	
a)	Road Junction Condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. — N.A			Yes/No	
f)				Yes/No	
g)				Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			√S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/stones/Pavement road markings are provided and maintained - on your			Yes/No	
4.	Compliance History				
a)	Status of ATR'	s & any others	ATR	Not pendi	

Overall Rating:

Satisfactory(S)	9
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

NAME: - Er. Amal prakash

Executive Engineer
R.W.D. Works Division
Kishangani-1