## FIELD INSPECTION REPORT

Date of Inspection: -82-42-20			Di	District: - Kishangani		
Division: - Kighan panj-1			Le	Length(km): - 4,38 k·M		
	of the Road:		adah			
	e/Programme:	MAINTENAN				
Packag	e No .: MR-N/19-	20/ Kishmany-1	106	Road Id No.: 21205802066		
	of the Project:		Ongoing/Completed /Under Maintenance			
Work is	s a case of:	New Connec	tivity/	Up gradation / Maintenance		
\$1. No	Parame		ers to be checked		Remarks	
1.	Pavement					
a)	Road Junction Condition					
b)	Condition of Surfacing					
c)	Riding Quality					
d)	Road Camber					
e)	Whether free from defects such as visible cracks, exposed aggregates					
	in case of CC Pavement. — N· A					
f)	Contraction Joints Provided or not (CC Pavement) N. A					
g)	Compaction of fland / shop & raincuts if any- ongoing					
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its Painting					
b)	Condition of A	~\$/SRI/U				
c)	Condition of ra	√S/SRI/U				
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m					
	Whether sign boards/informatory/cautionary Board/km & 200m  Yes/No stones/Pavement road markings are provided and maintained - ongoing					
4.	Compliance H	istory		9	)	
a)	Status of ATR's	s & any others		ATR	Not pendi	

## Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

(Signature)

NAME: Radheshyam projapati J.E., R.W.D., Kizhanganj-1