FIELD INSPECTION REPORT

Date of	Inspection: - OS	2-12-20	District: Kishonganj		
Division: - wishansani-1			Length(km): - 3.10 KrM		
	of the Road: Pw	D Rosard To	s Lohiya romdar path		
Scheme	Programme:	MAINTENANCE			
Package	e No .: MR - N/19-2	oficietangoni 11/05	Road Id No.: 21205901003		
	of the Project:	Ongoing/Comp	oleted /Under Maintenance		
Work is	a case of:		rity/ Up gradation / Maintenance		
\$1. No			s to be checked	Remarks	
1.	Pavement			/S/U	
a)	Road Junction Condition			-S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality				
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement NA				
f)	Contraction Joints Provided or not (CC Pavement) - N A				
g)	Compaction of flancky shope& raincuts if any - ongoing			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting S/SRI/I				
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating:

Satisfactory(S)	-5-
Satisfactory but requires Improvement (SRI)	- 14
Unsatisfactory(U)	_

NAME: Er. Amal proakather

Exisimat Veyincer
R.W.D. Works Division
Kishanganj-1