

## FIELD INSPECTION REPORT


<b>Date of Inspection:</b> - 02-12-20		<b>District:</b> - Kishangang
<b>Division:</b> - Kishangang-I		<b>Length(km):</b> 2.580 km
<b>Name of the Road:</b> Mumala chowk to Bishampur		
<b>Scheme/Programme:</b>	MAINTENANCE	
<b>Package No.:</b> MRN/19-20/Kishangang-I/05	<b>Road Id No.:</b> 2/205901012	
<b>Status of the Project:</b>	✓ Ongoing/Completed /Under Maintenance	
<b>Work is a case of:</b>	New Connectivity/ Up gradation / Maintenance ✓	

Sl. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. - N.A	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement) - N.A	Yes/No
g)	Compaction of flank / shop & raincuts if any - ongoing	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting - ongoing	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained - ongoing	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	Not pending.

**Overall Rating :**

<b>Satisfactory(S)</b>	S
<b>Satisfactory but requires Improvement (SRI)</b>	-
<b>Unsatisfactory(U)</b>	-

  
 02/12/20  
 (Signature)

**NAME:** Er. Radheshyam prajapati  
 J.E, R.W.D, Kishangang-I