FIELD INSPECTION REPORT

	ENDER HON REPORT		
Date of I	nspection: 02/12/2020 District: Krishangau : Krishangaus 2 Length (km): 3.19.	2	
Division	: Kishongaus - 2 Length (km): 3.19.		
Name of	the Road: To3 to laxuipur		
Scheme/	Programme: MAINTENANCE New Policy. No.: Road Id No.: 212059020	10	
Package	in the Maintenance Olygott	9'	
	The Project: Ongoing Completes and Ingradation/ Maintenance		
Work is	a case of: New Connectivity/Op graduation	Remarks	
Sl. No.	Parameters to be checked		_ +
1.	Pavement	S/U U	andly expected
a)	Road Junction condition	S/U ()	Body effects of a RISOD 2020 work just stanted
b)	Condition of Surfacing	S/U U	work the ad
c)	Riding Quality	S/U U	Men bolich.
d)	Road Camber visible cracks, exposed	Yes/No	Hen bolich.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
-	Contraction Joints provided or not (CC Pavement)		-
f)	Compaction of flank/slope & raincuts if any	Yes/No	
g)			
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	1245246	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ·	
4.	Compliance History	新华森市区	
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Ramanand Yadar.
Junior Engineer
Dighal Brank.