FIELD INSPECTION REPORT

Date	e of Inamed	THE RESERVE TO STATE OF THE PERSON OF THE PE	REPORT	-	
Divi	e of Inspection :	02.12. 2020 Distri	1 1		
Neshangary - 2 Length (km): 5.50 Km					
Scheme/Programme: MAINTENANCE Name of the Road: Kalupara to Magurjaan Railway Station 1 mgs					1024
Package No.: Road Id No.: 2120 590 8036					
Stati	as of the Project:	Ongoing/Completed/Under) 9 2	
	Work is a case of: New Connectivity/Up gradation/ Maintenance				
SI. N	lo.	Parameters to be chec	ked	Remarks	
1.	Pavement		d Think with	Alphon II	
a)	Road Junction condition			S/U ✓	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.	
g)	Compaction of flank/slope & raincuts if any			Yés/No .	
2	Cross Drainage	- Table			
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U		
c)	Condition of railings/słab/approach for Bridges		S/SRI/U		
-3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance Hist	ory	"我们,我们是是		
a)	Status of ATR's &	any others			

Overall Rating :

Satisfactory (S)	STERRI
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME:

Scanned with CamScanner