

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020		District: Kishanganj	
Division : Kishanganj-2		Length (km): 35.00 Km	
Name of the Road: Belwa to Supa Highway NH 39 WB border Raiganj Via Dhamelban			
Scheme/Programme: MAINTENANCE		Pothia Kishanganj (Part B)	
Package No.:		Road Id No.: 21205908040	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance			
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Transferred to RRP II

N.A.

N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Kur
2-12-2020
(Signature)

NAME: