

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: ARARIA.	
Division :		Length (km): 0.800 km.	
Name of the Road: Morbaila Amhera to Hanjua.			
Scheme/Programme:		MAINTENANCE ✓	
Package No.:		Road Id No.: 21206108002	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	Not started	S/U
b)	Condition of Surfacing	Not started	S/U
c)	Riding Quality	Not started	S/U
d)	Road Camber	Not started	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N/A		Yes/No
f)	Contraction Joints provided or not (CC Pavement) N/A.		Yes/No
g)	Compaction of flank/slope & raincuts if any N/A.		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained N/A		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	_____
Satisfactory but requires Improvement (SRI)	"SRI"
Unsatisfactory (U)	_____

NAME:

Chandra Sheela Singh  
Asst. Engineer  
RWD/F&Bs.

3/12/2020  
(Signature)  
03/12/2020  
J.E