

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: ARARIA
Division : FORBESGANJ		Length (km): 0.80 km.
Name of the Road: Morbulla H. 021 hq. to Ranna.		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21206108003
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Upgradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Not started
b)	Condition of Surfacing	"
c)	Riding Quality	"
d)	Road Camber	"
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Cross Drainage	N/A
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	Not started
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	←
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	←

NAME:

Chandra Shekhar Singh
Asst. Engineer
RWO/FBG

03/12/2020
(Signature)
03/12/2020
J.E