

FIELD INSPECTION REPORT

New maintenance under construction

Date of Inspection : 02-12-2020		District: SIWAN
Division : SIWAN - 2		Length (km): 1.46
Name of the Road: Guttani Darauli Road to Ramodra		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance <u>on going</u>	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S S/U
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	N.A Yes/No
2.	Cross Drainage	<u>work in progress</u>
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>work in progress</u>
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

<input checked="" type="checkbox"/> Satisfactory (S)	(S)	S
<input type="checkbox"/> Satisfactory but requires Improvement (SRI)		
<input type="checkbox"/> Unsatisfactory (U)		

NAME:

DESIGNATION:

for
3-12-2020
Executive Engineer
Rural Work Department
Work Division Siwan-2

for
02-12-2020
I.E
(Signature)

for
02/12/2020
A.E.