

FIELD INSPECTION REPORT

New Maintenance

Date of Inspection : 02-12-2020		District: SIWAN
Division : Siwan-2		Length (km): 1.70 km
Name of the Road: Guthani Sahagra road to Bakulari		
Scheme/Programme: MAINTENANCE		
Package No.:		
Status of the Project:	Road Id No.:	
Work is a case of:	Ongoing/Completed/Under Maintenance under Maintenance	
New Connectivity/Up gradation/ Maintenance Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A
2.	Cross Drainage	Yes/No OK
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No OK
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating

☒ Satisfactory (S)	S
☐ Satisfactory but requires Improvement (SRI)	
☐ Unsatisfactory (U)	

NAME:

DESIGNATION:

For
3.12.20
Executive Engineer
Rural Work Department
Work Division Siwan-2

2/12/2020
J.E.
(Signature)
Aph
02/12/2020
A.E.