FIELD INSPECTION REPORT

Date of Ir	spection: 2/12/2020 District: Muzsfarpur.	and the second s
Division:	R.W. D MUZ. east -1 Length (km): 0,900 km	
Name of	he Road: Balilleara hobind etwara Bazar Road towar	
Scheme/P	rogramme: MAINTENANCE	
Package	No.: Road Id No.:	
	the Project: Ongoing/Completed/Under Maintenance	
Work is a	case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	ا/كل
b)	Condition of Surfacing	√ S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Mo

Overall Rating :

Satisfactory (S)	121
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: KUNILKUMAR
DESIGNATION: J.E