

# FIELD INSPECTION REPORT

Date of Inspection : 2.12.20		District: Vaishali	
Division : MAHAR		Length (km): 3.01CH	
Name of the Road: Chandi Sarai Bichuli Mahadul Tola via Mahadul Dahan Pokhar		Road Id No.: 31507705002	
Scheme/Programme: MAINTENANCE		NEW Haintul Policy	
Package No.:		Road Id No.: 31507705002	
Status of the Project: Ongoing/Completed/Under Maintenance		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	NA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	NA Yes/No
g)	Compaction of flank/slope & raincuts if any	No Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

*Handwritten Signature*  
2/12/20  
(Signature)

NAME: Brajesh Kumar

DESIGNATION: Assistant-Engineer  
Jalandhar.