

# FIELD INSPECTION REPORT

Date of Inspection : 2.12.20		District: vaishali
Division : Mahmur		Length (km): 3.17
Name of the Road: Bahsi Neem Road to Narhar Pur		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.: 31507708037	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S
c)	Riding Quality	U
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S
f)	Contraction Joints provided or not (CC Pavement)	NA
g)	Compaction of flank/slope & raincuts if any	NA
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes/No
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Yes/No
c)	Condition of railings/slab/approach for Bridges	Yes/No
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

*Handwritten signature*  
2/12/20

(Signature)

NAME: Brajesh Kumar

DESIGNATION: Assistant Engineer  
Jalandhar.