


FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District: Vaishali
Division : Mahanagar		Length (km): 3.0 K.M
Name of the Road: Hajipur Mahanagar SH Gardariya chowk to Mohanpur		
Scheme/Programme: MAINTENANCE		MMRST Road
Package No.: N.A	Road Id No.: 31507708039	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓	
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. N.A	Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting N.A	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N.A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges N.A	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


02.12.2020
(Signature)

NAME: SHRABAN KUMAR PRASAD

DESIGNATION: A. E. R. W. D