

FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Vaishali
Division : Mahaga	Length (km): 1.70 K.M
Name of the Road: Gagan Kaji Patti Chandani Chowk to M.S Mohanpur Hote	
Scheme/Programme: MAINTENANCE	Hume Mohanpur Samudayik Bhawan Tak.
Package No.: N.A	Road Id No.: 31507708045
Status of the Project: Ongoing/Completed/Under Maintenance	✓
Work is a case of: New Connectivity/Up gradation/ Maintenance	✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A
f)	Contraction Joints provided or not (CC Pavement)	N.A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A
c)	Condition of railings/slab/approach for Bridges	N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)
Shailendra Kumar
2/12/20

NAME: Shailendra Kumar
DESIGNATION: J.E RWD Bidupur.