

# FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020		District: Vaishali
Division : Mahnagar		Length (km): 13.60 K.M
Name of the Road: Mahanagar to Bhayni Math Path.		
Scheme/Programme: MAINTENANCE		
Package No.: H.A	Road Id No.: 31507708054	
Status of the Project: Ongoing/Completed/Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/ Maintenance ✓		
Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. H.A	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement) N.A	✓Yes/No
g)	Compaction of flank/slope & raincuts if any N.A	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	HO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shailendra Kumar  
21/12/20  
(Signature)

NAME: Shailendra Kumar  
DESIGNATION: J.E, RWD, Bidupur.