

# FIELD INSPECTION REPORT

|                                                               |                               |
|---------------------------------------------------------------|-------------------------------|
| Date of Inspection : 02-12-2020                               | District: NALANDA             |
| Division : Bihar                                              | Length (km): 2.26 KM.         |
| Name of the Road: NH-82 (Rana Bighe) To Stadium Jail Gate.    |                               |
| Scheme/Programme: MAINTENANCE                                 | New Maintenance Policy - 2018 |
| Package No.:                                                  | Road Id No.:                  |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                               |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                               |

| Sl. No. | Parameters to be checked                                                                                             | Remarks               |
|---------|----------------------------------------------------------------------------------------------------------------------|-----------------------|
| 1.      | <b>Pavement</b>                                                                                                      |                       |
| a)      | Road Junction condition                                                                                              | S/U S                 |
| b)      | Condition of Surfacing                                                                                               | S/U S                 |
| c)      | Riding Quality                                                                                                       | S/U S                 |
| d)      | Road Camber                                                                                                          | S/U S                 |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NA             |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No NA             |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No Yes            |
| 2.      | <b>Cross Drainage</b>                                                                                                |                       |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U } NA          |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U               |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U               |
| 3.      | <b>Road Furniture</b>                                                                                                |                       |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No Yet to be done |
| 4.      | <b>Compliance History</b>                                                                                            |                       |
| a)      | Status of ATR's & any others                                                                                         | NIL                   |

Overall Rating :

|                                             |    |
|---------------------------------------------|----|
| Satisfactory (S)                            | S  |
| Satisfactory but requires Improvement (SRI) | NA |
| Unsatisfactory (U)                          |    |

02/12/2020  
(Signature) A. K.

NAME: Arvind Kumar  
DESIGNATION: Junior Engineer