FIELD INSPECTION REPORT

Date of Inspection:	02/12/2020	District: Nalander		
Division: Bikou	headar	Length (km): 0.660KM.		
Name of the Road:	Utarthy-Katt	trahi Road to Schakpur village in Bind		
Scheme/Programme	MAINTENANCII			
Package No.:		Road Id No.:		
Status of the Projec		Ongoing/Completed/Under Maintenance		
Work is a case of:	R New Connectivity/Up gradation/ Maintenance			
SI. No.	Parame	eters to be checked Remarks		

Sl. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	SAL		
b)	Condition of Surfacing	SAY		
c)	Riding Quality	S/U		
d)	Road Camber	SAY		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
2.5	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRE/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/ŞRI/U		
. 3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No		
14.1	Compliance History			
a)	Status of ATR's & any others	-40-		

Overall Rating

Satisfactory (S)	٤.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1 - 7

(Signature)

NAME: Mukesh Yadas

DESIGNATION: J.C

Scanned with CamScanner