FIELD INSPECTION REPORT

Date of Inspection: 02/12	12020 District: Natanda			
Division: Biharshar	Length (km): 3.950 Km.			
Name of the Road: Mouronea Budge To Swarchale.				
Scheme/Programme: MA	INTENANCE U			
Package No.:	Rond Id No.:			
Work is a case of: Nev	New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parnmeters to be checked	Remarks	
1.	Pavement	12	
a)	Road Junction condition	SID	
b)	Condition of Surfacing	SAS	
c)	Riding Quality	S/J	
d)	Road Camber	S/J	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRL/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRIAL	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.00	Compliance History	PINA 1	
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1 2

(Signature)

NAME: Mucesh Maday

DESIGNATION: J. G.

Scanned with CamScanner