

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: East Champaran	
Division : Avery		Length (km): 3.016	
Name of the Road: Madhubani math Se Dubey tala			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 31708202108	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No	
g)	Compaction of flank/slope & raincuts if any	NO Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M. K. Kumar
03.12.20
(Signature)

NAME: Mahendra Kumar

DESIGNATION: A.E.