

FIELD INSPECTION REPORT

Date of Inspection :	03-12-2020	District:	East Champaran
Division :	Axeroj	Length (km):	2.890
Name of the Road:	Sangrampur Block 8e Jalaha road to H		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	31708202213
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S S/U	
b)	Condition of Surfacing	S S/U	
c)	Riding Quality	S S/U	
d)	Road Camber	S S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No	
g)	Compaction of flank/slope & raincuts if any	No Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	Satisfactory
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
03-12-2020

(Signature)

NAME: Jitendra Kumar

DESIGNATION: J.E.