

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: East Champaran	
Division : Arera P.W.D.		Length (km):	
Name of the Road: Arera P.W.D. Road to English gram			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.: 31708202058	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	N/A	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	Maintenance Board Not Found.
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

dlas
02/12/2020
(Signature)

NAME: Harendra Lal

DESIGNATION: AE RWD
Paharpur