FIELD INSPECTION REPORT

Date of Inspection : 6	0.10.000	District: W. Champare	11)	
Date of Inspection: 02.12.2020 Division: Betaah		Length (km): L. 50 K. F.		
Name of the Road: Manthaulia to ward wank B.T load				
Scheme/Programme:	MAINTENANCE			
Package No.: RM/WE/RET/19/0019 Road Id No.: 31808808059				
Status of the Project:		pleted/Under Maintenance Completted		
Work is a case of:				
SI No.	Parameters to	bochecked	Remarks	
1. Pavement			A MARIA PARA	
a) Road Junction	Road Junction condition			
b) Condition of S				
c) Riding Quality	Riding Quality S			
d) Road Camber	S			
e) Whether free aggregates in c	Whether from from 1 C			
	Contraction Joints provided or not (CC Pavement)			
Control of the Contro	Compaction of flank/slope & raincuts if any			
2 Cross Drainag	Cross Drainage			
a) Condition of he	Condition of head walls in Hume pipe culverts including its painting			
	Condition of Abutment & Wing walls, Slab in RCC culverts			
是位于140分钟。1414年20年4年16日第二次,1414年16日第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十	Condition of railings/slab/approach for Bridges			
EXPERIENCE TO THE PROPERTY OF			The state of the s	
stones/Pavemen	boards/informatory/ot road markings are	cautionary Board/km & 2001 provided and maintained	n Yes/No	
4. Compliance Hi	fory		The reserve the second	
a) Status of ATR's	& any others	·	170	

Overall Rating

, how	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SUNIL KUMAR

DESIGNATION: JUNLOR ENGLHEER