FIELD INSPECTION REPORT

Date of					
Division: Betah			Length (km): 3.30 K. M		
Name of the Road: Are rof fwo to Harding Gast.					
Scheme	Programme:	MAINTENANCE			
Package No.: RMWE/BET/19/0018			Road Id No.: 31808902004		
			ed/Under Maintenance (onepletted		
Work is a case of:		New Connectivity/Up gradation/ Maintenance Main Lananco		1. 100 mg 現場所に関する 1. 1 1. 1 1. 1 1. 1 1. 1 1. 1 1. 1 1.	
Sl. No.		Parameters to	be checked	Remarks	
1	Pavement		Million State Commence	1	
a)	Road Junction	condition	S	S/U	
b)	Condition of S	urfacing	S .	S/U	
c)	Riding Quality			S/U	
d)	Road Camber S			S/U	
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	g e rsieki külenik			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b) .	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Roza Burniu	re (
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance H	istory		terms and the second	
a)	Status of ATR'	s & any others	A CONTRACTOR OF THE PARTY OF TH	071	

Overall Rating

T. C. Z.	4
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: SUNIC RUMAR

DESIGNATION: JUNIOR BASINEER