## FIELD INSPECTION REPORT

Date of Inspection: 02-12-2020		District: WEST CHAMPARAN
Division: BAGAHA-1		Length (km): 8.50 KM
Name of the Road: :- 1	3HATAURA TO K	umhiyA
Scheme/Programme:	MAINTENANCE 3054 (MR) NEW MAINTENANCE POOL	
Package No.: MR-NIS	- Bayaha. 1/04	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

OF THE STATE OF TH	New Connectivity/Op gradation Maintenance	w Connectivity/Op gradation/ with the connectivity/Op gradation/	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	<b>48/</b> U	
b)	Condition of Surfacing	<b>\8/U</b>	
c)	Riding Quality	<b>\$</b> /U	
d)	Road Camber	<b>√</b> S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/Ne	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Xes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	√8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	√3/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	¥cs/No	
4.	Compliance History		
a)	Status of ATR's & any others	Mo	

Overall Rating :

Satisfactory (S)	(8)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: - MD. SHAHANSHAH ALAM

DESIGNATION: J.E