FIELD INSPECTION REPORT

· · · · · · · · · · · · · · · · · · ·		
Date of Inspection: 02-12-2020		District: WEST CHAMPARAN
Division: BAGAHA-J		Length (km): 3.910 Km
Name of the Road: p	W) ROAD TO K	ARTANÎA
Scheme/Programme:	MAINTENANCE - 3054(MR) NEW MAINTENANCE POLICY	
Package No.: MR-NI	9-20 Begaha-1/06	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	√8/ U
c)	Riding Quality	√8 /U
d)	Road Camber	√8 /U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	√es/No
2.	Cross Drainage	In the second
a)	Condition of head walls in Hume pipe culverts including its painting	∜SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√8/SRI/U
c)	Condition of railings/slab/approach for Bridges	√S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	√s/No
· 4.	Compliance History	
a)	Status of ATR's & any others	. 0

Overall Rating :

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: my, Shahenshin Alam

DESIGNATION: J.E