

FIELD INSPECTION REPORT

Date of Inspection : 2-12-2020	District: Darbhanga
Division : Darbhanga-1	Length (km): 5.00 km
Name of the Road: Pandasara to Hichal Path	
Scheme/Programme:	MAINTENANCE
Package No.: MR 3054.	Road Id No.: 31909208149
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No No
g)	Compaction of flank/slope & raincuts if any	Yes/No No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U —
c)	Condition of railings/slab/approach for Bridges	S/SRI/U —
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No.
4.	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(U)

Note:- Agreement terminated due to Non Maintenance of road vide E.E letter No. 434 dt. 27.02.2020. Revised estimate already submitted to Dept

(Signature) 02/12/2020

NAME: Vineet Kumar

DESIGNATION:

Assistant Engineer
R.W.I (W) Subdiv Bahadurpur / Itanagar nagar