

FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020 District: Darbhanga
 Division : Darbhanga-1 Length (km):
 Name of the Road: P.W.D Path to Ghonghatta Jame Wali Path me Kataw Repair work.
 Scheme/Programme: MAINTENANCE
 Package No.: MR (3054) Road Id No.: 31909208150
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance (Protection work)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(S)

Note:- Work is of only construction of Protection wall. No road is involved in estimate. Also Provision of 5 yr. Maintenance is not in agreement.

5/12/2020
 (Signature)

NAME: Vinod Kumar

DESIGNATION: A.E.
 Bahadurpur.