

# FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA-2	Length(Km):	0.820 K.M.
Name of Road:	NH-57 SASTRI CHOWK SE P.W.D. PATH.		
Scheme/Programme:	Maintenance MR- 3054.		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	<b>Pavement</b> BT		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓	
c)	Riding Quality	S/U ✓	
d)	Road Camber	S/U ✓	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement (CC PAVEMENT)	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank /slope & raincuts if any	Yes/No ✓	
2	<b>Cross Drainage</b>		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U NA	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA	
3	<b>Road Furniture</b>		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓	
3	<b>Compliance History</b>		
a)	Status of ATR's & any others	NO	
Overall Rating:			
Satisfactory (S)		—	
Satisfactory but requires Improvement (SRI)		—	
Unsatisfactory (U)		U	

Heavily Submergence & flow of water during flood period total constructed length was fully damaged & at about end point road was washed out.

Name:

Designation:

As per Guideline given by SEC-RWD (GOB) for early movement of vehicle temporary restoration work has been done.

(Signature)

*[Signature]*  
03/12/20  
A.E. Singhwara