

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Madhubani
Division : Benipatti	Length (km): 1.30 km
Name of the Road: Karhi Naykerhi to Bakulwa	
Scheme/Programme: MAINTENANCE under New Maint. Policy	
Package No.: MR/MA/BEN/19/09	Road Id No.: 31310001014
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SU
b)	Condition of Surfacing	✓ SU
c)	Riding Quality	✓ SU
d)	Road Camber	✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <i>ongoing</i>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <i>NA</i>
g)	Compaction of flank/slope & raincuts if any	Yes/No <i>ongoing</i>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>NA</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>NA</i>
c)	Condition of railings/slab approach for Bridges	S/SRI/U <i>NA</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <i>ongoing</i>
4.	Compliance History	
a)	Status of ATR's & any others	<i>Not any</i>

Overall Rating :

Satisfactory (S)	<i>S</i>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Indira
03/12/20
(Signature)

NAME: *Md. Sami*

DESIGNATION: *J.E. R.W.D. Works div Benipatti*
Section Benipatti