FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020			District: Patro		
		tua	Length (km): 3.850		
Name of	the Road: Dan	riyawan Se Jeev	anchate Bhaya Kazibigha To	ate Path	
-	Programme:	MAINTENANCE	V V		
Package No.:		otel Road Id No.:			
Status of the Project:		Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
Sl. No.	A	Parameters to	be checked	Remarks	
1,	Pavement				
a)	Road Junction condition			✓S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√8/U	
d)	Road Camber			✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No MA	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No 🗚	
g)	Compaction of flank/slope & raincuts if any			Xes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			√ 8/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			✓S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U NA	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance I				
a)	Status of ATR's & any others			NO	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Himanshu Roj DESIGNATION: Assistant Engineer